
Licensing Inspection Report (Annual Inspection)

Facility: CEDARSTONE, ENHANCED CARE

Address: 378 YOUNG ST.
TRURO NS, B2N 7H2

Date(s) of Inspection: August 12 &13, 2020

Requirements resulting from licensing inspection:

1. LTCPR 7.5.1.b
The licensee shall ensure compliance with all applicable government inspection processes, policies, standards, requirements and service agreements, including but not limited to, the following authorities: Department of Labour and Advanced Education, including Occupational Health and Safety (OHS).
2. LTCPR 8.1.4
The licensee shall ensure resident and family satisfaction surveys are conducted a minimum of annually.
3. LTCPR 12.2.2.2.c
The licensee shall ensure aesthetic, functional and surface integrity of the following are maintained: interior building components such as, but not limited to, partitions, ceilings, doors, casework, coatings and sealants.
4. LTCPR 9.2.4.a
The licensee shall ensure there is a documented Fire Safety Plan, in accordance with the National Fire Code, that is reviewed a minimum of annually and revised as necessary to ensure the plan is current.
5. LTCPR 9.2.10
The licensee shall ensure a written record for fire drills and exercises outlined above, that includes the date, time, location, staff attendance, response times, outcomes, areas for improvement, remedial actions and debriefing, is maintained by the licensee.
6. HSCR 38(2), LTCPR 8.5.3
The licensee shall ensure medications are stored in a secure and appropriate manner, accessible only to persons authorized to administer medications.