



Labour and Advanced Education
Technical Safety Division

Fuel Safety Regulations

Fuel Safety Bulletin

(Issued pursuant to s.30 of the *Technical Safety Act*)

Bulletin Number: FS18-02

ISSUE DATE: February 8, 2018

Rev #

Date:

REPEAL DATE:

SUBSECTION:

ISSUED BY: Paul Fowler, Chief Fuel Safety Inspector

SUBJECT: Regency Ultimate U39 Direct Vent Gas Stove

We have recently become aware of an issue with some models of the above noted gas stove. The manufacturer is advising anyone who has a stove of this type to immediately stop using the stove and shut off the gas supply to it. This Product Advisory pertains to the Regency Ultimate U39 Direct Vent Gas Stove line of fireplaces, which includes model numbers U39-NG10, U39-NG1 and U39-LP1 manufactured between January 1, 2011 and January 18, 2018 with serial numbers 315004536 to 315012548.

More information on the possible hazard and what to do is available on the manufacturers website at:

www.regency-fire.com/U39notice

For any questions regarding this Bulletin, please contact me at our Dartmouth offices.

All Fuel Safety Bulletins can be viewed online at: <https://novascotia.ca/lae/fuelsafety/fuelbulletins.asp>

Paul Fowler
Chief Inspector, Fuel Safety