



SAFETY BULLETIN



Safety Bulletin Number: **0000005**

Issued February 25th, 2021 by Paul Fowler, Chief Inspector, Fuel Safety
Department of Labour and Advanced Education

Fuel Safety Directive

Legal information

Issued pursuant to section 30 of the Technical Safety Act

Summary

Due to recent observations by Fuel Safety inspection staff, this Fuel Safety directive is being issued to all propane suppliers to remind their delivery personnel of the code requirement to remain at the container being filled during the transfer process.

Directive

In accordance with clause 5.2.2 of the CSA B149.2-15 code: *while propane is being transferred from one container to another, the person transferring shall remain at the container being filled.*

Delivery drivers must remain at the container being filled during the entire transfer operation. This means the driver must remain physically at the point of transfer (the point where the delivery hose connects to the container being filled), in order to prevent hazards such as accidental container overfilling, container or valve failure, etc.

Sources

[Technical Safety Act](#)

Contact for bulletin queries

Safety Branch
Labour and Advanced Education
1-800-952-2687