SAMPLING AND ASSAY PLAN OF WILNOFF SHAFT

showing

THE VEIN IN PLANE

Property of
Boston and Goldenville Gold Mining Company
Shier's Gold District, Moose-Head, Halifax County N.S.

Part of the Report by:
A. A. Hassan
Mining Geologist and Consulting Engineer.
Completed in New-York City, June 19th 1913.

◆ Consult Legend of the Main Shaft ◆





Outcrop

Outcrop

Anticlinal Pitch 15° to 18° East

55'

16.5'

Stope Up 5°

Visible Gold

Average Strike of Vein
5° S. of E.

Average Dip of Vein
44° S.

Stope Down 8°

$6.30

$23.40

$1.90 per ton

Visible Gold

Visible Gold

On West Stope at Roof Breast
Qz 13", S.2", Qz 1", S.4½"
F.W. Qz ½"

Middle Breast
S. on H.W. 1", Qz 12", S.1", Qz 1",
S. 6½". F.W. Qz ½"

Corner
Qz 8", S.3", Qz 1",
S. 8½".

3' along H.W. Slate 1", Qz 11", S.8"

½ foot from corner Qz 9", S.½", Qz 4½", S.1", Qz 10", S.1", Qz 4½", S.1", Qz 5", S.9"

3' down H.W. S.1", Qz 10", S.8" F.W. Qz 1"

In corner H.W. S.1", Qz 10", S.8½"

On joint H.W. S.1", Qz 10", S.1", Qz 2", S.6½"

1' from W. corner on Bottom Qz 9", S.1", Qz 5", S.6"

No Hulk taken Qz 12"

Qz 5", S.1", Qz 5", S.1", Qz 1", S.4½"

S.1", Qz 10½", S.1", Qz 3", S.6½"

1 foot from E. corner Bottom Qz 10", S.1", Qz 2", S.6"

1' from E. corner of E. Stope
Qz .8", S.2", Qz 2", S.7"

Middle of Breast
Qz 10", S.3", Qz 1", S.7"

Bottom of Breast
Qz .10", S.4", Qz ½", S.7"

3 feet along bottom of Stope
Qz .10", S.1", Qz 1", S.10"

In corner of Stope
Qz 12", S.7", F.W. Vein 1"

Near Corner
Qz 10½", S.1", Qz 7", S.4", Qz 1", S.6"

Down 3 feet
Qz .10", S.4", Qz ½", S.5"

Along 3' (1' from corner)
Qz 11", S.1", Qz 1", S.
Qz ½", S. 6½"

Middle next vertical
Qz .13", S.10"
(Vein very wide)

In Middle Horizontal Bench last to bottom
Qz 12", S.1", Qz 1", S.7"

Halfway up 11. stope 2' from Bottom
Qz 8", S.2", Qz 2"
S.1", Qz 1", S.4", Qz 1", S.2"

1 2 3 4 5' 10' 15' 20' 25'

Scale: One Inch equal Five Feet.

41-1