
Licensing Inspection Report (Semi-Annual Inspection)

Facility: MUSQUODOBOIT VALLEY HOME FOR SPECIAL CARE ASSOCIATION

Address: 126 HIGGINSVILLE RD.
MIDDLE MUSQUODOBOIT NS, B0N 1X0

Date(s) of Inspection: March 5, 2020

Requirements resulting from licensing inspection:

1. LTCPR 12.1.6
The licensee shall ensure hazardous products that may be harmful to residents are secured at all times and are not accessible to residents. They are stored and disposed of in accordance with established safety practices/manufacturers' recommendations.
2. HSCR 38(2), LTCPR 8.5.3
The licensee shall ensure medications are stored in a secure and appropriate manner, accessible only to persons authorized to administer medications.
3. LTCPR 8.1.6
The licensee shall ensure the results of the satisfaction survey are summarized, with resident/authorized designate/family identifiers removed, and are available and easily accessible for viewing.
4. LTCPR 6.7.2.c
The licensee shall ensure a recreational program is developed and implemented that is flexible, innovative and varied to respond to the residents' leisure needs and interests.
5. LTCPR 6.5.2.c
The licensee shall ensure the following processes are developed and followed: labeling of food in refrigerators and discarding of expired food.
6. LTCPR 12.2.2.2.c
The licensee shall ensure aesthetic, functional and surface integrity of the following are maintained: interior building components such as, but not limited to, partitions, ceilings, doors, casework, coatings and sealants.

7. LTCPR 8.4.10

The licensee shall ensure if bars of soap and other personal care items are used in resident rooms, they are designated for the use of one resident and are not shared.