

Labour and Advanced Education

Building, Fire and Technical Safety Division

DIRECTIVE

(issued pursuant to s.30 of the *Technical Safety Act*)

Directive Number	TSA - 002
Statute	
Regulation	Fuel Safety Regulations
Section Name	Oil installation compliance inspection
Section	87
Sub-section	
Issued by	Dale Stewart, Fuel Safety Chief Inspector
Approved by	David Wigmore, P.Eng., Administrator
Date of Directive	December 14, 2011
Effective Date	December 14, 2011
Repeal Date	
Version	1.0
Directive Details	

Directive Details

For the purposes of implementation of the Fuel Safety Regulations, the enforcement of s. 87 of the regulations is delayed until July 1, 2012.

The delay is in response to concerns that have been brought forward that the details of the inspection program have not been developed to the extent that there would be compliance with the requirement.

During this period of delay, the Building, Fire and Technical Safety Division will continue to provide education and notification of the change. The Division will provide support to the heating oil suppliers to develop a program including the procedures and training necessary to comply with this provision.

This Directive replaces Directive TSA - 001, Version 1.0, dated March 28, 2011.