



CONTOUR INTERVAL = 5'  
 ELEVATION OF COLLAR, DAN SHAFT, TAKEN AS ZERO

PLAN  
 OF  
 PERCY AND PARTINGTON MINES  
 SCALE 1"=30'  
 JUNE 4, 1928  
 SEAL HARBOUR NS  
 DRAWN BY G.W.M.