

APPENDIX H

MISCELLANEOUS PHOTOGRAPHS





PHOTO NO. H-1: Security flagging around excavation at No. 2 Raise during construction period.



PHOTO NO. H-2: Safety berms constructed around No. 1 and No. 2 Raises.

PROJECT NO. 10903





PHOTO NO. H-3: Foundations of former hoist room used as reference elevation for survey.



PHOTO No. H-4: Bolt in hoist room foundation used as reference elevation.

PROJECT NO. 10903





PHOTO NO. H-5: Obtaining elevations of monolithic concrete slab over No. 1 Raise.



PHOTO NO. H-6: Obtaining elevations of pre-cast concrete panels and cast-in-place concrete cap over No. 2 Raise.

PROJECT NO. 10903





PHOTO NO. H-7: Concrete truck preparing to deliver concrete to No. 1 Shaft.



PHOTO NO. H-8: Obtaining concrete test cylinders to determine compressive strength of concrete.

PROJECT NO. 10903

