

APPENDIX B

AQUATIC SURVEY PHOTOGRAPHS



Photograph 1: WC-1 Channel immediately downstream of existing culvert



Photograph 2: Channel downstream of the proposed crossing on WC-2 (Haight Brook)



Photograph 3: Substrate at transect of WC-2 (Haight Brook)



Photograph 4: Upstream transect with cobble substrate on WC-2 (Haight Brook)



Photograph 5: Downstream transect with sandy-silt substrate on WC-2 (Haight Brook)



Photograph 6: WC-2 (Haight Brook) culvert downstream looking upstream



Photograph 7: Proposed crossing location WC-3, upstream of headwaters of Haight Brook